MARTIN

COOLANT RECOMMENDATION CHART

| MATERIAL | DRILLING | MILLING | TAPPING | TURNING |
|-----------------------------|-------------------------------|--|---|--|
| Aluminum | Soluble oil (70-90% water) | Soluble oil (96% water) or mineral oil | 25% sulfur-based oil mixed with mineral oil | Mineral oil with 10% fat or soluble oil |
| Alloy Steel | Soluble oil | 10% lard oil with 90% mineral oil | 30% lard oil with 70% mineral oil | 25% sulfur base oil with 75% mineral oil |
| Brass | Soluble oil | Soluble oil (96% water) | 10-20% lard oil with mineral oil | Mineral oil with 10% fat or soluble oil |
| Bronze | Soluble oil | Soluble oil | 30% lard with mineral oil | Soluble oil |
| Cast Iron | Dry | Dry | Dry of 25% lard oil with 80% mineral oil | Dry |
| Copper | Soluble oil | Soluble oil | Soluble oil | Soluble oil |
| Low Carbon & Tool Steels | Soluble oil | Soluble oil | 25-40% lard oil with mineral oil | 25% lard oil with 75% mineral oil |
| Malleable Iron | Soluble oil | Soluble oil | Soluble oil | Soluble oil |